


Category	Bedside Light
Product name	Bunky - Bedside Light Recall
Product description	We have recently become aware of 2 possible safety issues with Bunky. If the head of the lamp is covered by a blanket or duvet, it can overheat, and could cause a minor burn. If the lamp is not unplugged before replacing the CFL tube, it could result in an electric shock. As Europe's leader in child-safe lighting, these risks, though small, are unacceptable to us. We are not aware of any injuries being caused by these problems, but we are still asking anyone who has bought a Bunky to return it to us for free of charge replacement and reimbursement of your postage costs. Important: Bunky is still one of the most child-safe reading lamps available. While waiting for your replacement, please do not put an ordinary lamp with a GLS or a Halogen bulb within your child's reach unless it has been specifically designed for a child's bedroom.
Model or Type	Model Numbers: 6910 and 6910R on sale since January 2006
Picture	
Instructions	While waiting for your replacement, please do not put an ordinary lamp with a GLS or a Halogen bulb within your child's reach unless it has been specifically designed for a child's bedroom. For free replacement, and reimbursement of your postage, please return your Bunky Bedside Light direct to: Spearmark International Ltd, Howard Road, Eaton Socon, St Neots, PE19 8GA Please do not return your Bunky to the shop where you bought it, they will not be able to give you a replacement. For more information please either: Phone: 01480 222324 or Email: <a href="mailto:bunky@spearmark.co.uk">bunky@spearmark.co.uk</a> We sincerely apologise for any inconvenience caused by this recall.
Comments	Important: Bunky is still one of the most child-safe reading lamps available.
Date	15/8/2008