


Category	Electrical Appliances
Product name	Senseo coffee makers
Brand	Philips
Model or Type	Senseo coffee makers
Country of Origin	China
Picture	
Risk type	Electric shock, burns and injuries
Risk Description	In rare cases, where extreme scale has built up and if the appliance incurs an additional electrical fault, pressure build-up could cause the unit to come apart suddenly. This could cause injuries from steam, flying parts or exposure to live parts.
Affected Products	Philips has identified a safety problem affecting a number of Senseo coffee makers produced between July 2006 and November 2008.
Identifying Your Product	The affected product type numbers are: HD7805 HD7810 HD7811 HD7812 HD7814 HD7816 HD7820 HD7822 HD7823 HD7824 HD7830 HD7832 HD7841 HD7842
Instructions	Philips has advised consumers to: Check the sticker on the base plate of the appliance for the type-number (e.g. HD7820) and the date code (e.g. 09123), and If the type-number matches one of those listed above, contact the company by either visiting its website at <a href="http://www.senseorepair.ie">www.senseorepair.ie</a> or call the freephone number 1800 818 834, giving details and the date code Philips has also advised that consumers could check online, if a unit is affected, by registering the product and providing contact information. Additional information and instructions on the product recall are also available on the above website.
Date	16/04/2009

